

## Contents

|  |     |
|--|-----|
| Preface  | vii |
| SMITH, B. J., GOMEZ-HERAS, M. & VILES, H. A. Underlying issues on the selection, use and conservation of building limestone  | 1   |
| CASSAR, J. The use of limestone in a historic context – the experience of Malta  | 13  |
| CALVO, J. P. & REGUEIRO, M. Carbonate rocks in the Mediterranean region – from classical to innovative uses of building stone  | 27  |
| SIEGESMUND, S., GRIMM, W.-D., DÜRRAST, H. & RUEDRICH, J. Limestones in Germany used as building stones: an overview  | 37  |
| ESPINOSA-MARZAL, R. M. & SCHERER, G. W. Mechanisms of damage by salt   | 61  |
| MILLER, A. Z., LEAL, N., LAIZ, L., ROGERIO-CANDELERIA, M. A., SILVA, R. J. C., DIONÍSIO, A., MACEDO, M. F. & SAIZ-JIMENEZ, C. Primary bioreceptivity of limestones used in southern European monuments | 79  |
| RUIZ-AGUDO, E. & RODRIGUEZ-NAVARRO, C. Suppression of salt weathering of porous limestone by borax-induced promotion of sodium and magnesium sulphate crystallization                                  | 93  |
| BECK, K. & AL-MUKHTAR, M. Weathering effects in an urban environment: a case study of tuffeau, a French porous limestone   | 103 |
| STEFANIDOU, M. A. Approaches to the problem of limestone replacement in Greece   | 113 |
| DOTTER, K. R. Historic lime mortars: potential effects of local climate on the evolution of binder morphology and composition  | 119 |
| IOANNOU, I., PETROU, M. F., FOURNARI, R., ANDREOU, A., HADJIGEORGIOU, C., TSIKOURAS, B. & HATZIPANAGIOTOU, K. Crushed limestone as an aggregate in concrete production: the Cyprus case                | 127 |
| BECK, K., BRUNETAUD, X., MERTZ, J.-D. & AL-MUKHTAR, M. On the use of eggshell lime and tuffeau powder to formulate an appropriate mortar for restoration purposes                                      | 137 |
| PÁPAY, Z. & TÖRÖK, Á. Physical changes of porous Hungarian limestones related to silicic acid ester consolidant treatments   | 147 |
| FIGUEIREDO, C., FOLHA, R., MAURÍCIO, A., ALVES, C. & AIRES-BARROS, L. Pore structure and durability of Portuguese limestones: a case study   | 157 |
| VAZQUEZ-CALVO, C., VARAS, M. J., ALVAREZ DE BUERGO, M. & FORT, R. Limestone on the ‘Don Pedro I’ facade in the Real Alcázar compound, Seville, Spain   | 171 |
| FIGUEIREDO, C., AIRES-BARROS, L. & NETO, M. J. The church of Santa Engrácia (the National Pantheon, Lisbon, Portugal): building campaigns, conservation works, stones and pathologies                  | 183 |
| BUJ, O., GISBERT, J., FRANCO, B., MATEOS, N. & BAULUZ, B. Decay of the Campanile limestone used as building material in Tudela Cathedral (Navarra, Spain)  | 195 |

|   |     |
|---|-----|
| RESCIC, S., FRATINI, F. & TIANO, P. On-site evaluation of the 'mechanical' properties of Maastricht limestone and their relationship with the physical characteristics                          | 203 |
| SEARLE, D. E. & MITCHELL, D. J. The effect of combustion-derived particulates on the short-term modification of temperature and moisture loss from Portland Limestone                           | 209 |
| MOTTERSHEAD, D., FARRIS, P. & PEARSON, A. The changing Maltese soil environment: evidence from the ancient cart tracks at San Pawl Tat-Tarġa, Naxxar  | 219 |
| THORNBUSH, M. J. Measurements of soiling and colour change using outdoor rephotography and image processing in Adobe Photoshop along the southern façade of the Ashmolean Museum, Oxford        | 231 |
| SASS, O. & VILES, H. A. Two-dimensional resistivity surveys of the moisture contents of historic limestone walls in Oxford, UK: implications for understanding catastrophic stone deterioration | 237 |
| Index   | 251 |